Mounting Options 5000 Series

Quick Start Guide

P/N 6011693, Rev. C May 2023







5000 Series Wall Mounting Kit (5000-WMK)

Components

ltem	TSI [®] Part #	Description	Qty.
1	5000-WMBP	Wall Mounting Back Plate	1
2	5000-WMMP	Wall Mounting Meter Plate	3
3	N/A	M3 Stainless Screws	3
4	N/A	#8 Stainless Screws	2



Assembly

1. Mount the Back Plate to the desired wall location (screws not supplied).



2. Attach the Meter Plate to the Meter using the three (3) supplied M3 screws.



(continued on next page)

 Slide the top two holes of the attached Meter Plate into the wall-mounted Back Plate.



 Use one (1) supplied #8 screw in the bottom frontfacing screw hole to secure the instrument.



Wall Mounting DIN Rail Kit (5000-WMDRK)

Components

ltem	TSI [®] Part #	Description	Qty.
1	5000-WMMP	Wall Mounting Meter Plate	1
2	N/A	M3 Stainless Screws	3
3	N/A	#6 Stainless Screws	4
4	5000-WMDRC	DIN Rail Adapter	2



Assembly

 Attach the two (2) DIN Rail Adapters to the Wall Mount Meter Plate using the four (4) supplied #6 Stainless Screws.



2. Attach the Wall Mount Meter Plate to the Meter using the three (3) supplied M3 screws.



3. Attach the mounted DIN Rail Adapters to the DIN Rail.



5000 Series Tabletop Stand (5000-TTS)

Components

ltem	Description	Qty.
1	Tabletop Stand	1
2	M3 Stainless Screws	3



Assembly

 Attach tabletop stand to meter using the three (3) supplied M3 screws.



(continued on next page)

2. Secure to workbench or wall by inserting screws (*not supplied*) through screw holes.



TSI and TSI logo are registered trademarks of TSI Incorporated in the United States and may be protected under other country's trademark registrations.



TSI Incorporated - Visit our website www.tsi.com for more information.

 USA
 Tel: +1 800 680-1220

 UK
 Tel: +44 149 4 459200

 France
 Tel: +33 1 41 19 21 99

 Germany
 Tel: +49 241 523030

 India
 Tel: +91 80 67877200

 China
 Tel: +86 10 8219 7688

 Singapore
 Tel: +65 6595 6388

P/N 6011693 Rev C ©2023 TSI Incorporated



Printed in U.S.A.